



**Site:**  
Building #1  
**Address:**  
47 Data Road  
Augusta, Maine

**Tested by:**  
curtisWorks Communications Solutions  
www.curtisWorks.com  
207-621-8146

**Written notes:** Various faults included as samples of testing capabilities

**Cable ID:** Building: Office: 1 Written notes:

**Qualified:** ✓ Coax (75 ohm)

Date	Time	Length	Version	S/N
12/8/2005	12:49:31 PM	321 m	V0.05.04	00000005

**Cable ID:** Building: Office: 100 Written notes:

**Qualified:** ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; Wiremap Only; Telco

Date	Time	Length	Version	S/N
12/8/2005	4:25:59 PM	16.0 m	V0.05.06	8734030



**Cable ID:** Building: Office: 101 Written notes:

**Qualified:** ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; Wiremap Only; Telco

Date	Time	Length	Version	S/N
12/8/2005	4:42:19 PM	37.7 m	V0.05.06	8734030




**Cable ID:** Building: Office: 102 Written notes:

**Qualified:** ✓ 10BASE-T; Wiremap Only; Telco  
**Disqualified:** ✗ 1000BASE-T  
✗ 100BASE-TX  
✗ Voice Over IP

Reason: Crosstalk fault @ 18.9 m  
Reason: Crosstalk fault @ 18.5 m  
Reason: Crosstalk fault @ 18.5 m

Date	Time	Length	Version	S/N
12/8/2005	1:05:27 PM	50.2 m	V0.05.04	00000005



**Cable ID:** Building: Office: 103 Written notes:

**Qualified:** ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; Wiremap Only; Telco

Date	Time	Length	Version	S/N
12/8/2005	1:22:42 PM	34.6 m	V0.05.04	00000005



**Cable ID:** Building: Office: 104 Written notes:

**Qualified:** ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; Wiremap Only; Telco

Date	Time	Length	Version	S/N
12/8/2005	1:38:55 PM	18.8 m	V0.05.04	00000005





**Site:**  
Building #1  
**Address:**  
47 Data Road  
Augusta, Maine

**Tested by:**  
curtisWorks Communications Solutions  
www.curtisWorks.com  
207-621-8146

**Written notes:**

**Cable ID:** Building: Office: 105 Written notes:

**Qualified:** ✓ Wiremap Only; Telco  
**Disqualified:** ✗ 1000BASE-T Reason: Excessive Length  
✗ 100BASE-TX Reason: Excessive Length  
✗ 10BASE-T Reason: Excessive Length  
✗ Voice Over IP Reason: Excessive Length

Date	Time	Length	Version	S/N	
12/8/2005	1:56:18 PM	321 m	V0.05.04	00000005	

**Cable ID:** Building: Office: 106 Written notes:

**Qualified:** ✓ 10BASE-T; Wiremap Only; Telco  
**Disqualified:** ✗ 1000BASE-T Reason: Crosstalk fault  
✗ 100BASE-TX Reason: Crosstalk fault  
✗ Voice Over IP Reason: Crosstalk fault

Date	Time	Length	Version	S/N	
12/8/2005	3:11:29 PM	11.0 m	V0.05.04	00000005	

**Cable ID:** Building: Office: 107 Written notes:

**Disqualified:** ✗ 1000BASE-T Reason: Wiremap  
✗ 100BASE-TX Reason: Wiremap  
✗ 10BASE-T Reason: Wiremap  
✗ Voice Over IP Reason: Wiremap  
✗ Wiremap Only Reason: Wiremap  
✗ Telco Reason: Wiremap

Date	Time	Length	Version	S/N	
12/8/2005	3:36:32 PM	13.4 m	V0.05.04	00000005	

**Cable ID:** Building: Office: 108 Written notes:

**Qualified:** ✓ Telco  
**Disqualified:** ✗ 1000BASE-T Reason: Wiremap (Split Pairs)  
✗ 100BASE-TX Reason: Wiremap (Split Pairs)  
✗ 10BASE-T Reason: Wiremap (Split Pairs)  
✗ Voice Over IP Reason: Wiremap (Split Pairs)  
✗ Wiremap Only Reason: Wiremap (Split Pairs)

Date	Time	Length	Version	S/N	
12/8/2005	3:52:13 PM	20.6 m	V0.05.04	00000005	

**Cable ID:** Building: Office: 109 Written notes:

**Qualified:** ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; Wiremap Only; Telco

Date	Time	Length	Version	S/N	
12/8/2005	4:02:58 PM	30.9 m	V0.05.06	8734030	